

Libby Asbestos Superfund Site
Summary of USACE-Owned Properties
Prepared from Response Manager as of 7/13/17

EPA Property ID	EPA Address	Samples collected or response taken?	Documentation	Current Status	Comments
AD-000139	17877 MT Highway 37 (GID 7920)	Yes	Completion Form - interior cleaning	Removal Completed	interior cleaning due to vermiculite in dam crawlspace area; no further action required
AD-008418	GID 4499	No		Inspection Not Required	property includes roadway and campground/boat launch area
AD-007152	GID 5210	Yes	Samples collected in the right-of-way of Highway 37 only	Inspection Not Required	property includes roadway and campground/boat launch area
AD-007328	GID 6699	No		Inspection Not Required	property includes roadway and boat launch area
AD-007457	GID 7751	No		Inspection Not Required	property includes roadway and campground
AD-006931	GID 3811	No		Inspection Not Required	
AD-007994	GID 4934	No		Inspection Not Required	
AD-007170	GID 5330	No		Inspection Not Required	